




Polk st roof

Annotation Report

Report created on March 8, 2018



		Annotation	Distance	Area	Volume	Cut	Fill
1	●	Moisture 1- Priority Rating 2		903.63 ft ²			
2	●	Moisture 9- Priority Rating 2		137.35 ft ²			
3	●	Moisture 7- Priority Rating 2		58.88 ft ²			
4	●	Moisture 10- Priority Rating 2		394.71 ft ²			
5	●	Moisture 2- Priority Rating 2		701.81 ft ²			
6	●	Moisture 8- Priority Rating 2		95.69 ft ²			
7	●	Moisture 11- Priority Rating 2		270.71 ft ²			
8	●	Moisture 12- Priority Rating 2		40.58 ft ²			
9	●	Moisture 6- Priority Rating 2		233.04 ft ²			
10	●	Moisture 41- Priority Rating 2		265.55 ft ²			
11	●	Moisture 29- Priority Rating 2		272.11 ft ²			
12	●	Moisture 30- Priority Rating 2		34.44 ft ²			
13	●	Moisture 27- Priority Rating 2		354.56 ft ²			
14	●	Moisture 17- Priority Rating 2		192.03 ft ²			
15	●	Moisture 40- Priority Rating 2		70.61 ft ²			
16	●	Moisture 39- Priority Rating 2		260.70 ft ²			
17	●	Moisture 26- Priority Rating 2		53.60 ft ²			
18	●	Moisture 28- Priority Rating 2		21.96 ft ²			
19	●	Moisture 25- Priority Rating 2		48.44 ft ²			
20	●	Moisture 24- Priority Rating 2		137.02 ft ²			
21	●	Moisture 38- Priority Rating 2		26.91 ft ²			
22	●	Moisture 42- Priority Rating 2		62.11 ft ²			
23	●	Moisture 37- Priority Rating 2		384.92 ft ²			
24	●	Moisture 32- Priority Rating 2		92.78 ft ²			
25	●	Moisture 33- Priority Rating 2		170.72 ft ²			

26	●	Moisture 31- Priority Rating 2	21.20 ft ²
27	●	Moisture 23- Priority Rating 2	103.66 ft ²
28	●	Moisture 22- Priority Rating 2	77.07 ft ²
29	●	Moisture 21- Priority Rating 2	117.22 ft ²
30	●	Moisture 5- Priority Rating 2	57.26 ft ²
31	●	Moisture 4- Priority Rating 2	31.75 ft ²
32	●	Moisture 3- Priority Rating 2	53.50 ft ²
33	●	Moisture 13- Priority Rating 2	39.40 ft ²
34	●	Moisture 14- Priority Rating 2	125.61 ft ²
35	●	Moisture 15- Priority Rating 2	187.72 ft ²
36	●	Moisture 16- Priority Rating 2	94.94 ft ²
37	●	Moisture 18- Priority Rating 2	42.19 ft ²
38	●	Moisture 19- Priority Rating 2	50.38 ft ²
39	●	Moisture 36- Priority Rating 2	198.70 ft ²
40	●	Moisture 20- Priority Rating 2	412.58 ft ²
41	●	Moisture 34- Priority Rating 2	73.41 ft ²
42	●	Moisture 35- Priority Rating 2	43.81 ft ²
43	●	Moisture 46- Priority Rating 2	160.49 ft ²
44	●	Moisture 45- Priority Rating 2	57.05 ft ²
45	●	Moisture 48- Priority Rating 2	56.62 ft ²
46	●	Moisture 47- Priority Rating 2	58.34 ft ²
47	●	Moisture 51- Priority Rating 2	44.67 ft ²
48	●	Moisture 50- Priority Rating 2	26.05 ft ²
49	●	Moisture 49- Priority Rating 2	19.70 ft ²
50	●	Moisture 56- Priority Rating 2	183.63 ft ²
51	●	Moisture 57- Priority Rating 2	104.09 ft ²
52	●	Moisture 53- Priority Rating 2	182.99 ft ²
53	●	Moisture 52- Priority Rating 2	22.93 ft ²

54	●	Moisture 43- Priority Rating 2	297.62 ft ²
55	●	Moisture 44- Priority Rating 2	27.77 ft ²
56	●	Moisture 54- Priority Rating 2	120.77 ft ²
57	●	Moisture 55- Priority Rating 2	27.77 ft ²
58	●	Moisture 59- Priority Rating 2	125.40 ft ²
59	●	Moisture 58- Priority Rating 2	105.92 ft ²
60	●	Moisture 64- Priority Rating 2	39.61 ft ²
61	●	Moisture 60- Priority Rating 2	34.44 ft ²
62	●	Moisture 61- Priority Rating 2	49.84 ft ²
63	●	Moisture 67- Priority Rating 2	75.89 ft ²
64	●	Moisture 66- Priority Rating 2	820.53 ft ²
65	●	Moisture 63- Priority Rating 2	14.64 ft ²
66	●	Moisture 65- Priority Rating 2	21.20 ft ²
67	●	Moisture 62- Priority Rating 2	219.80 ft ²
68	●	Roof A	29975.34 ft ²
69	●	Roof B	10731.51 ft ²
70	●	Whole Roof System	40834.62 ft ²
71	●	Moisture 68- Priority Rating 2	72.23 ft ²
72	●	Moisture 69- Priority Rating 2	68.78 ft ²
73	●	Moisture 70- Priority Rating 2	322.70 ft ²
74	●	Moisture 70- Priority Rating 2	133.04 ft ²
75	●	Moisture 71- Priority Rating 2	84.07 ft ²
76	●	Moisture 76- Priority Rating 2	64.48 ft ²
77	●	Moisture 77- Priority Rating 2	42.19 ft ²
78	●	Moisture 78- Priority Rating 2	36.06 ft ²